Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0884

Agency: SWHRA

AGENCY INFORMATION

Address: 1574 White AVE

Henderson, TN

Agency Contact: Oliver, Jerry

Address:

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-225-5436

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Alt. Client ID: 16016SW-0884

Work Order Name:

Version 8.5.0 Page 1 of 4

Report Run On: 5/24/2010

Measures

	Measure 1 Infilt	ration Redctn			Componer	ıts			Inspected
C	omment								
					Estimated			Actual	.,,,
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal pipes under kitchen sink, Seal behind washer and dryer, Seal ceiling in back bedroom. (tape and mud} Master bedroomSeal pipes under vanity. Seal crown molding around kitchen cabinets	Each	1					
2	Labor	Labor	Hour		000000000000000000000000000000000000000				
3	Construction Materials/Hardwar e	Seal pipes under hall bath. Seal closet wall behind tub. Caulk sides of manel to fireplace	Each	1	Total and the second				
4	Labor	Labor	Hour			**************************************			
5	Construction Materials/Hardwar e	Mastic duct boots	Each	1			To the state of th		
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Replace broke sash on W-2 window, Replace broke pane on W3 window	Each	1					
8	Labor	Labor	Hour						
0	ther Detail								
					The state of the s				
			I	Measur	e Sub Total:		5	Sub Total:	
	Field Notes:								

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Measure 2 Atti	c Ins. R-30			Component	ts A1		ı	nspected
Comment								
		1114-	04	Estimated	Total		Actual Unit Cost	Total
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	ıotai	Qty	Omit Cost	10tai
1 Insulation	Attic Insulation - Blown Cellulose - Add 10 inches	SqFt	1221					
2 Labor	Labor	Hour	1221					
3 Construction Materials/Hardware	Install attic access cover	Each	1					
4 Labor	Labor	Hour						
Other Detail		promote the second	gamenta sasta and a construction of	, , ,		,	ļ-	
	,							
			Measur	e Sub Total:			Sub Total:	
Measure 3 DW	H Pipe Insulation			Componen	ts		i	Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail		·				1	MATERIAL STATE OF THE STATE OF	
						<u> </u>		
] [
		Measure Sub Total: St					Sub Total:	
Field Notes:			11 A MATERIAL CO. 10 A TOTAL CO. 10					

Client Name:

Client ID:

Alt. Client ID: 16016SW-0884

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 4

Measure 4 CO Monitor is Needed				Componen	Inspected				
C	comment				Estimated	r		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					No. of Particular States and Stat
	Other Detail			Measur	e Sub Total:			Sub Total:	
	Field Notes:								
L	Work Order Grand Total: Grand Total:							7/3/11/3 BBB 14/4/7/7/4/4/11/11	